

1 / 70







FIG.1

2 / 70



3/70




FIG. 5

4/70




FIG. 6

5770




FIG.7

6/70





FIG. 8

7 / 70



8/70





FIG.10

9/70



10 /70




FIG. 12

11 / 70




FIG.13




FIG.14




FIG.15

12/70




FIG.16

13/70




FIG.17

14/70




FIG. 18




FIG. 19

15 / 70




FIG. 20




FIG. 21

16 / 70




FIG. 22

17 /70




FIG.23

18 /70




FIG.23a




FIG.23b

19/70




FIG.23C

20 /70





FIG.24



21 / 70





FIG. 25

22/70




FIG. 26

23 / 70




FIG.27

24 /70




FIG.28

25 /70




FIG.29

26 / 70




FIG.30

27 /70




FIG.31

28 / 70




FIG.32

29 /70




FIG.33

30 /70






FIG.34

31 /70




FIG.35

32 /70




FIG.35a

33 /70





FIG.35b

34 /70



35 / 70




FIG. 36b




FIG. 36a

36 /70





FIG.37



37 /70





FIG.38



38 /70





FIG.39



39 /70




FIG.40

40 /70




FIG.41

41 / 70







FIG.42



42 / 70



43 /70




FIG.44

44 /70




FIG.45

45 /70




FIG.46




FIG.47

47 /70





FIG.48



48 /70




FIG.49

49 /70




FIG.50

50 /70




FIG.51

51 /70




FIG.52

52 /70




FIG.53

53 /70




FIG.54

54 /70





FIG.55

55 / 70



56 /70




FIG.57

57 /70





FIG.58

58 /70



59 /70




FIG.60

60 /70


6

FIG.61

61 / 70




FIG.62

62 /70




FIG.63

63 /70




FIG.64

64 /70




FIG.64b




FIG.64a

65 /70




FIG.65

66 /70




FIG.66

67 /70





FIG.67

68 /70



69 /70




FIG.69

70 /70




FIG.70